Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/50005DE2174/1
Work Order Type: Weatherization
Audit Name: Audit (13)

CLIENT INFORMATION

Client Name: JAMES, MILLIE

Address:
Client ID: 50005DE2174

Alt. Client ID:

CLIENT CONTACT INFORMATION

JAMES, MILLIE (901) 877-6872 Applicant/Person of Record

AGENCY INFORMATION

Agency: Delta Human Resource Agency

Agency Phone: (901) 476-5226

Address: P. O. Box 634 **Fax:** (901) 476-5258

Agency Contact: Martin, Darrell L. Work Phone:

Cell Phone: (901) 262-8090

Email Address: DarrelllMartin@bellsouth.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Upstairs under construction. Foundation is only 12" from ground.

Client Name: JAMES, MILLIE Client ID: 50005DE2174 Alt. Client ID: Work Order (Bid Form)
Work Order Name: WO/50005DE2174/1

DOE Weatherization Assistant Version 8.5.0 Page 1 of 5

Report Run On: 5/24/2010

Measures

	Measure 1 Report	olace door unit at rear do	oor		Component	ts		ı	nspected
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					
0	ther Detail								
	and Dotain								
				Measur	e Sub Total:]	Sub Total:	
	Field Notes:						-		
	omment Caulk V	Itration Redctn Windows #3 & #4 erstrip Door (Front)			Componen	ts		1.	nspected
	omment Caulk V				Component Estimated			I. Actual	nspected
C	omment Caulk V	Vindows #3 & #4	Units	Qty			Qty		nspected
C (omment Caulk Weathe Material / Labor Miscellaneous	Vindows #3 & #4 erstrip Door (Front)	<i>Units</i> Each		Estimated		Qty	Actual	
# 10	omment Caulk Weather Material / Labor Miscellaneous Supplies	Windows #3 & #4 erstrip Door (Front) Description / Comment		Qty	Estimated		Qty	Actual	
# 10	omment Caulk Weathe Material / Labor Miscellaneous	Windows #3 & #4 erstrip Door (Front) Description / Comment		Qty	Estimated		Qty	Actual	
# 10	omment Caulk Weather Material / Labor Miscellaneous Supplies	Windows #3 & #4 erstrip Door (Front) Description / Comment		Qty	Estimated		Qty	Actual	
# 10	omment Caulk Weather Material / Labor Miscellaneous Supplies	Windows #3 & #4 erstrip Door (Front) Description / Comment	Each	Qty 1	Estimated Unit Cost			Actual	
# 10 C	omment Caulk Weather Weather Material / Labor Miscellaneous Supplies	Windows #3 & #4 erstrip Door (Front) Description / Comment	Each	Qty 1	Estimated			Actual Unit Cost	
# 10 C	omment Caulk Weather Material / Labor Miscellaneous Supplies	Windows #3 & #4 erstrip Door (Front) Description / Comment	Each	Qty 1	Estimated Unit Cost			Actual Unit Cost	
# 10 C	omment Caulk Weather Weather Material / Labor Miscellaneous Supplies	Windows #3 & #4 erstrip Door (Front) Description / Comment	Each	Qty 1	Estimated Unit Cost			Actual Unit Cost	

Actual ty Unit Cost	
Unit Cost	
	Total
Sub Total:	
	Inspected
	Total
ty Unit Cost	I OTAL
	, 5 (4)
	, 5 (4)
Sub Total:	.500
	Sub Total:

Comment Replace# Material / Labor0 Refrigerators	20cu refrigerator Description / Comment			Estimated			Actual	
	Description / Comment						Actual	
	2000 paon a Commont	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
o ixemgerators		Each	1		, ota,			70147
	-	Lacii	'					
Other Detail			1					
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
	Insulation			Componen	ts E1,N1	,S1,W1	/	nspected
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1022					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
						'		
Field Notes								
Field Notes:								

Report Run On: 5/24/2010

Measure 7 Stor	m Windows			Componen	ts WD2,	WD1,W	/D8	nspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Storm Window	SqFt	25.68					
2 Labor	Storm Window	SqFt	25.68					
3 Other	Storm Window	Each Window	3					
Other Detail							<u> </u>	
			Measure	e Sub Total:] ;	Sub Total:	
Field Notes:								
Measure 8 CO Comment	Monitor is Needed			Componen				Inspected
Comment				Estimated	1		Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected
Comment	Description / Comment	<i>Units</i> Each		Estimated	1	Qty	Actual	
Comment# Material / Labor1 Health and Safety	Description / Comment		Qty	Estimated	1	Qty	Actual	
Comment# Material / Labor1 Health and Safety Items	Description / Comment CO monitor	Each	Qty 1	Estimated	1	Qty	Actual	
Comment# Material / Labor1 Health and Safety Items2 Labor	Description / Comment CO monitor	Each	Qty 1	Estimated	1	Qty	Actual	
Comment# Material / Labor1 Health and Safety Items2 Labor	Description / Comment CO monitor	Each	Qty 1	Estimated	1	Qty	Actual	
Comment# Material / Labor1 Health and Safety Items2 Labor	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated	1		Actual	
Comment# Material / Labor1 Health and Safety Items2 Labor	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor 1 Health and Safety Items 2 Labor Other Detail	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor 1 Health and Safety Items 2 Labor Other Detail	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor 1 Health and Safety Items 2 Labor Other Detail	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor 1 Health and Safety Items 2 Labor Other Detail	Description / Comment CO monitor	Hour	Qty 1 1 Measure	Estimated Unit Cost	1		Actual Unit Cost	

Client Name: JAMES, MILLIE Client ID: 50005DE2174 Alt. Client ID:

DOE Weatherization Assistant Version 8.5.0 Page 5 of 5